STAT

Copy - of 6

10 November 1955

MENORANDUM FOR THE RECORD

SUBSTICT: MATS Shuttle Maintenance

while at exterious Strip on 7 November 1955, the Base Commander reported to me that one of the two maintenance men supplied to MATS from San Bernardino at Burbank for the shuttle was replaced by an inexperienced man. This change has resulted in insufficient care of the 2-5h and consequently several times the aircraft has been delayed in taking off because of mechanical failue. The Base Commander considers this a serious matter and asks Headquarters assistance in contacting Colonel Burg to effect pressure on San Bernardino to supply MATS with competent maintenance personnel.

Assistant Administrative Officer PCS/DCI

STAT

Orig - Watertown File

2 - OJR

3 - 8.0.

4 - Ope

5 - chrone

6 - reading

是在文字标题的数

ADMinah